



# FIRE RESISTANT TIMBER DOOR SCHEME

***Certificate number: IFCC 1364***

This is a product certificate to certify that

## ***UK Doorsets Ltd***

Unit 10, Spartan Ind Centre  
Brickhouse Lane  
Great Bridge, West Bromwich  
West Midlands B70 0DH  
Tel: 0121 521 2175

who fabricate the following timber fire doors & fire resistance timber based doorsets:

**Halspan FD30, FD60, Flamebreak FD30, FD60,  
Blankfort FD30, FD60, Strebord FD30, FD60,  
Stredor FD30, FD60, Moralt FD30, FD60,  
Vicaima FD30, FD60, Duocore FD30,  
Fibrecore FD30, Tri-Sound FD30, FD60  
Safehinge FD30, FD60, Deanta FD30**

have satisfied the requirements of the SDP01 Fire Resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 60 minutes integrity** are detailed on page 2 of this certificate.



Initial certification: 22 March 2018  
Revised: 07 January 2021  
Valid to: 21 March 2023  
Issue status: 3

Ian Woodhouse  
Director of Certification  
Page 1 of 3



175

IFC Certification Ltd  
20 Park Street, Princes Risborough, Buckinghamshire. England HP27 9AH  
Tel: +44 (0)1844 275500 Fax: +(0)1844 274002 E-mail: [info@ifccertification.com](mailto:info@ifccertification.com) Web: [www.ifccertification.com](http://www.ifccertification.com)  
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.

## ***Certificate number: IFCC 1364***

The production of fire resistance timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

<b>Doorset Description</b>	<b>Fire Rating</b>	<b>Assessment/Test Report</b>
Halspan Prima	FD30	HS01
Halspan Prima	FD60	HS02
Halspan Optima	FD30	HS03
Halspan Optima	FD60	HS04
Flamebreak 30	FD30	FEA/F98164
Flamebreak 60	FD60	Chilt/A02141, WF408272
Blankfort 30/30+	FD30	Chilt/A12151
Blankfort 60/60+	FD60	Chilt/A12152
STREBORD	FD30	Chilt/A02066, IFCA/08037
STREBORD	FD60	Chilt/A02067, IFCA/08038
STREDOR	FD30	CNA/F15159
STREDOR	FD60	WF377027
Safehinge	FD30 & FD60	Chilt A12005
Fibrecore	FD60	PAR/14658/01
Duocore	FD30	Chilt/A12296
Trisound	FD30	PAR/12033/01
Trisound	FD60	PAR/13088/01
Warmsprings	FD60, FD90, FD120	IFCA/07019
Moralt Laminesse Klassik & FireSmoke	FD30	PAR/14247/01
Moralt Laminesse FireSmoke & FireSafe	FD30	PAR/12519/01
Moralt Laminesse FireSmoke & FireSafe	FD60	PAR/12519/02
Moralt Laminesse FireSound	FD30 & FD60	PAR/14559/01
Moralt Laminesse FireSound	FD30 & FD60	PAR/12519/03
Vicaima	FD30	FEA/F99112A
Vicaima	FD60	Chilt/A13093
Deanta Type 1 & 2	FD30	WF399982
Deanta Type 3	FD30	WF399990
Deanta Type 4	FD30	WF399991
Deanta Type 5	FD30	WF399992



The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

**It is the certificates holder's responsibility to ensure that the latest version /revision of the above assessment/ test reports are maintained as part of the audited FPC system.**

**Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.**